



DATA ACCEPTANCE PROGRAM

UL Third-Party Test Data Program

Investigations of products by UL usually involve the testing of samples of the products. While UL maintains extensive facilities for these purposes, it is also possible to utilize third-party test facilities for testing of products under UL's Third-Party Test Data Program.

The laboratory must have in place a fully documented ISO/IEC 17025:2005 laboratory quality program, physical resources, equipment, qualified personnel and procedures needed to conduct the tests. The laboratory must be assessed by UL to ISO/IEC 17025:2005 and technical method demonstration before data can be accepted.

Initial and ongoing validation of testing methods must be performed. After the program is established, UL will reassess a test laboratory annually. All data submitted is thoroughly reviewed and audited by UL before being used for certification.

Should UL decide to pursue a third-party arrangement, the following are some of the considerations.

Requirements

Assessment of laboratory operations

The laboratory operations must have documented procedures and policies in place to assure accuracy and precision performing tests, obtaining data and reporting results.

The laboratory quality system shall be based on ISO/IEC 17025:2005 and encompass all elements of ISO/IEC 17025:2005. Additional UL requirements can be found at www.ul.com/dap > Resources > DAP Tools and are summarized below.

Subcontracting of tests

(ISO/IEC 17025:2005 Clause 4.5)

Under the Third-Party Test Data Program UL does not permit the further subcontracting of tests to other parties. If tests cannot be conducted at the recognized laboratory the work is to be returned to UL to determine an appropriate source for testing.

Purchasing services and supplies

(ISO/IEC 17025:2005 clause 4.6)

A participating laboratory must maintain procedures to purchase, inspect and store critical consumables. Any consumables must meet technical specifications as noted in the test standard. Please see UL document 00-OP-C0033 Laboratory Consumables for Client Labs and 00-OP-C0037 Thermocouple Wire Validation for Clients Labs at www.ul.com/dap > Resources > DAP Tools for more information.

Nonconforming tests or calibrations

(ISO/IEC 17025:2005 clause 4.9)

A participating laboratory is to have procedures in place to stop, evaluate and, when appropriate, resume testing when nonconforming test methods have been used. When nonconforming testing takes place, remedial action shall be taken, as appropriate. Based on the severity of the nonconforming tests, corrective action procedures may also be required to prevent a recurrence. This also applies to test equipment found to be out of tolerance prior to calibration. UL shall be notified of any impact to test data accepted by UL.

Corrective action

(ISO/IEC 17025:2005 clause 4.11)

A participating laboratory must have procedures in place to implement corrective actions when nonconforming testing, nonconforming calibrations or departures from the laboratory quality system policies and procedures are discovered. These corrective action procedures are to include root cause analysis, documentation of corrective actions and monitoring to assure that corrective actions have been effective. UL is to be notified if any test data is impacted.

Technical records

(ISO/IEC 17025:2005 clause 4.13)

Records are to be legible and stored and retained in such a way that they are readily retrievable. Storage must be in facilities that provide a suitable environment to prevent damage, deterioration or loss. Retained records are to include quality and calibration records and test data.

UL requires submittal of original data. If copies of data are submitted, a participating laboratory must retain records of original observations and derived data as well as sufficient information to establish an audit trail for each data sheet package sent to UL.

If an error is made in recording data, it is to be neatly lined out, the correct information recorded, the change initialed and a reason provided for the change. Erasures, correction tape or correction liquid are not acceptable. Please see UL document oo-OP-Coo25 Data Recording and Reporting for Clients Labs at www.ul.com/dap > Resources > DAP Tools for more information.

Accommodations and environmental conditions

(ISO/IEC 17025:2005 clause 5.3)

Test areas must have proper energy resources, lighting, temperature control, humidity control and other environmental conditions required to conduct tests. All participating laboratories shall effectively monitor and control those factors that affect testing. Please see UL documents oo-OP-Coo35 Laboratory Ambient Conditions for Clients Labs and oo-OP-Coo36 Laboratory Power Quality for Clients Labs at www.ul.com/dap > Resources > DAP Tools for more information.

Test equipment

(ISO/IEC 17025:2005 clause 5.5)

A participating laboratory must be furnished with test equipment sufficient to correctly perform tests in accordance with the applicable test standard or procedure. The equipment is to be at least as accurate as specified or implied in the test standard, or procedure or meet UL's minimum accuracy requirements as specified in UL document oo-OP-Coo34 Equipment Accuracy Requirements for Clients Labs at www.ul.com/dap > Resources > DAP Tools.

All equipment shall be in good working order and calibrated appropriately. Each instrument shall bear a calibration sticker with both the latest calibration date and the calibration due date.

Records maintained for each instrument and any automated software are to include:

- Full identification of equipment and records of its acquisition
- Detailed history of damage, malfunction, modification, maintenance and repair
- Calibration certificates
- Records demonstrating that equipment complies with specified tolerances
- Current location of equipment
- When appropriate, maintenance plan and all maintenance carried out to date
- Current version of all software, regardless of source, and validation records for any software developed and maintained by the laboratory

Measurement traceability

(ISO/IEC 17025:2005 clause 5.6.2)

Measuring equipment must be calibrated to a nationally or internationally recognized standard of measurement or standard reference material. When traceability is not possible, other procedures must be used to assure traceability in accordance with ISO/IEC 17025:2005. The calibration frequency shall be determined to assure required accuracy between calibrations. Generally, equipment shall be calibrated at least annually. Any limitations of usage should be clearly indicated.

Note: Test equipment calibration must be conducted by an accredited calibration laboratory. Calibration laboratories accredited by an ILAC, APLAC or EAC Mutual Recognition Agreement Signatory such as A2LA, NIST/NVLAP, UKAS, SCC, NATA, JCSS, JAB, DKD, JNLA and IAS. Please see UL document oo-OP-Coo32 Calibration Certificate Analysis for Clients Labs at www.ul.com/dap > Resources > DAP Tools for more information.

For laboratories that conduct calibrations for their own purposes, UL will assess traceability for compliance with ISO/IEC 17025:2005. For details of UL's requirements for in-house calibration laboratories, please see UL document 00-OP-Coo38 In-House Calibration Requirements for Clients Labs at www.ul.com/dap > Resources > DAP Tools for more information.

Reporting of results

(ISO/IEC 17025:2005 clause 5.10)

Participating laboratories are to record all observed data as well as a description of the test method or reference to the test method used, e.g., standard name, standard number, edition or issue date, latest revision date, clause and test name. Data are to be recorded in ink on form or standard laboratory data sheets. Personnel at participating laboratories should use form UL data sheets when available.

Use of non-UL form data sheets will require further review by UL to assure compliance with UL data recording procedures. UL may apply additional fees for review of non-UL datasheets. Data sheets must be reviewed for content prior to use by the laboratory.

- All instruments used to record test data or environmental conditions must be recorded and correlated to tests performed
- Customer identification, including location where tests were performed
- Signature of the laboratory signatory
- Sequentially numbered pages with the total number of pages recorded on the first page
- Typed or printed name of staff member performing the test on each data sheet where results are recorded. For test data collected electronically, only the typed name of the technician is required
- Any chart paper, computer paper, printouts and similar resources must include the same information as specified above
- Clear identification of which samples were used for testing. When multiple samples are used for one test, data sheet must clearly indicate result for each sample. When multiple samples are used for a test program of one model or type, unique identifiers must be used to distinguish between

tested samples tested. These unique identifiers are to be noted on the test datasheet.

- Rationale for not performing a test. The rationale should be provided as part of the datasheet package submittal or as a cover to the completed datasheet package.

Complete details can be found in UL document 00-OP-Coo25 Data Recording and Reporting for Clients Labs at www.ul.com/dap > Resources > DAP Tools.

Test method validation

Each test covered by the Third-Party Test Data Program will be verified through direct assessment of the facilities, equipment, and personnel. Demonstrating proper testing methods includes items such as placement and securement of thermocouples, use of instrumentation, use of appropriate environments including placement of the product in test jigs as described in standards, knowledge of situations that may produce erroneous data, etc.

Annually each test method is to be validated through direct demonstration during the annual assessment. At any time, UL can require repeat of testing at UL test laboratories or through the Witness Test Data Program at the participating testing laboratory. Some specific categories may require repeat testing or participation in a proficiency test program.

Oversight and audit

Laboratory responsibilities

It is a laboratory's responsibility to notify UL of any changes in equipment, personnel, etc., material to the program that take place between annual reassessments. Based on the changes, UL may decide to reassess the facility to reevaluate conformance with the program.

Each laboratory shall name at least one signatory. The laboratory signatory shall sign to each data package submitted to UL attesting that only qualified staff have been assigned to conduct tests, and that consumables, equipment, environment, and data recording and reporting meet UL's minimum requirements as specified above and in the documents located at www.ul.com/dap > Resources > DAP Tools.

Assessments

UL conducts annual assessments to the requirements detailed above. These assessments include validating test methods covered by UL's scope of recognition. Assessments and participation in the Third-Party Test Data Program are test- and standard specific. Participation is scoped by specific tests for specific standards. Laboratories not submitting test data under the Third-Party Test Data Program for more than one year will be reassessed prior to further acceptance of test data.

Test data submitted

All test data will be thoroughly reviewed and conformance with requirements determined by UL. Reviews include:

- Accuracy of sample(s) tested
- Accuracy of test method used
- Test results
- Test equipment used
- Data recording procedures
- Completeness of required testing
- Appropriateness of justification for tests not conducted

UL retains the right to countercheck test data at any time. Submittal of data does not mandate UL acceptance. Data can be counterchecked at UL or through the Witnessed Test Data Program.

Agreements

To formalize the relationship with UL, each participant must have appropriate agreements on file with UL. Agreements need to be completed and on file with UL prior to an initial assessment or acceptance of data.

How to apply

Laboratories interested in participating in the Third-Party Test Data Program should contact the UL Data Acceptance Program Customer Service team for further assistance. The DAP customer service team will arrange for the appropriate business sponsor to work with the laboratory interested in providing data to UL.