



PUBLIC NOTICE

Release No. 22PN-05

Peyton Zylke
Corporate Communications
UL
847.226.3483
Peyton.Zylke@ul.com

UL Warns of Unauthorized UL Marks on Fire Extinguishers

NORTHBROOK, IL, (April 30, 2022) — The following is a notification from UL that the Hyprex Fire Extinguishers identified below bear unauthorized UL Certification Marks. These fire extinguishers have not been evaluated by UL to the appropriate Standards for Safety and it is unknown if they comply with any safety requirements.

Name of Product: Hyprex Rapid Cooling Nano Technology Fire Extinguisher

Remedy: This product should be removed from service. UL recommends that users keep a UL Certified fire extinguisher in a readily accessible location to use in the event of a fire.

Identification on the Products:

The unauthorized UL Certification Mark appears on the extinguisher above the barcode.



Hyprex
Rapid Cooling Nano Technology
Fire Extinguisher
Model Hyprex 460
Manufactured by Ominyo

Photos:



Known to be Distributed by: Omniyo PTE LTD, Omniyo SDN BHD, and other online sellers on eCommerce platforms.

About UL

UL is a global safety science leader. We deliver testing, inspection and certification (TIC), training and advisory services, risk management solutions, and essential business insights to help our customers, based in more than 100 countries, achieve their safety, security, and sustainability goals. We believe our deep knowledge of products and intelligence across supply chains make us the partner of choice for customers with complex challenges. Discover more at [UL.com](https://www.ul.com).